



uTrack24 - AudioLan

Firmware 4078 Release Notes

Firmware Build 4078 (Dec 2017)

Firmware build 4078 has the following new features and fixes:

- Fixed SAP session browsing problems in some dynamic conditions
- Fixed SAP announcements which were having update problems in some dynamic conditions
- Fixed SAP reception "always-syntonzed" problem
- PTP master selection in dynamic conditions optimized
- PTP message queue optimized
- Added PTP slave-only option
- Added static DNS configuration
- Minor improvements in web UI
- General bug fixes and optimizations

Firmware Build 3864 (Feb 2017)

Firmware build 3864 has the following new features and fixes:

- SAP implementation allows interoperability with AES67 Dante devices
- New PTP packet filter for improved slave results
- New website with advanced features: SDP files, PTP status, PTP domain configuration, more status information
- SIP/unicast support (peer-to-peer SIP only, no server), receiver started connections only
- IP configuration changes checked for validity before storage
- Improvements towards better Bonjour updates when changing IP addresses in a controlled way (reboot button after static address changed, AutoIP to DHCP assignment).
- Some minor improvements to the web UI
- Improved internal webserver for concurrent accesses
- Corrected AutoIP behavior to assign always the same address, unless somebody else is using it.
- Improved Ethernet driver for the reception of packet bursts
- IP gateway is now configurable by the user
- Minor bug fixes and optimizations

Firmware Build 3139 (Feb 2015)

- Initial release