



# uTrack-X32

## Firmware Release Notes

### Firmware Build 5000 (Oct 2018)

#### Changes

- Fixed clicking issue when using the card at 48kHz with some new revisions of mixing consoles.

#### Bug Fixes:

- Problem with playback head positioning with uRemote for some long songs.

### Firmware Build 3865 (Feb 2017)

#### New Features:

- Playlists can be created in uTool and playback can be controlled with uRemote.
  - Instant playback available in Playlist. Song is pre-loaded and ready to be played back as soon as play button is clicked.
  - Set different start modes for each song in the playlist
  - Set the desired song order when creating playlist in uTool and edit the song order on the fly with uRemote.

#### Changes

- In folder single play mode, next song in the folder is selected after the current song playback is completed.
- Log file is created for recordings.
- Starting a new recording while recording is not allowed if the current recording is less than 1 minute
- USB drives with cluster size of less than 64KB not supported by the device.

### Firmware Build 2905 (Dec 2015)

#### Bug Fixes:

- Problems with starting a recording after doing a format of a fully loaded hard drive
- Recording and pre-recording not started due to temporary folder not being cleaned up properly
- Incorrect maximum stereo output channel number fixed

#### Changes

- Green Blinking LED for playing status
- LED turns red when hard disk space is less than 30 mins
- Recording button is responsive when the pre-recording is ongoing
- Support firmware update over USB sticks
- Optimized browsing with uRemote
- Shuffle mode improved